

DAFTAR PUSTAKA

- Adrian, J., Latif, N., Noerochim, L., & Kurniawan, B. A. (2016). Analisa Kerusakan Superheater *Tube Boiler* Tipe ASTM A213 Grade T11 pada Pembangkit Listrik Tenaga Uap. *Jurnal Teknik ITS*, 5(2), 148–152. <https://doi.org/10.12962/j23373539.v5i2.18561>
- Ahmad, J., Purbolaksono, J., & Beng, L. C. (2010). Failure analysis on high temperature superheater Inconel® 800 *tube*. *Engineering Failure Analysis*, 17(1), 328–333. <https://doi.org/10.1016/j.engfailanal.2009.06.013>
- Aini, N. N., Damis, C., & Nusyirwan, W. ; (n.d.). *Analisis Mekanisme Kegagalan pada Pipa Boiler Menggunakan Metode Root Cause Failure Analysis (RCFA)*. 494–501.
- Al Hajri, M., Malik, A. U., Meroufel, A., & Al-Muaili, F. (2015). Premature failure of dissimilar metal weld joint at intermediate temperature superheater *tube*. *Case Studies in Engineering Failure Analysis*, 3, 96–103. <https://doi.org/10.1016/j.csefa.2015.03.006>
- Antono, V. (2014). Analisa Kegagalan Platen *Tube* Superheater PLTU Teluk Sirih. *Power Plant*, 6.
- Ardy, H., Putra, Y. P., Anggoro, A. D., & Wibowo, A. (2021). Failure analysis of primary waste heat *Boiler tube* in ammonia plant. *Heliyon*, 7(2), e06151. <https://doi.org/10.1016/j.heliyon.2021.e06151>
- Assefinejad, A. H., Kermanpur, A., Eslami, A. M., & Kangazian, J. (2020). Failure investigation of water wall *tubes* in a drum *Boiler* of a thermal power plant. *Engineering Failure Analysis*, 118(March), 104869. <https://doi.org/10.1016/j.engfailanal.2020.104869>
- Chandra, K., Kain, V., & Dey, G. K. (2011). Failure of 2.25Cr-1Mo steel superheater *tubes* in a fluidized bed combustor due to fireside corrosion. *Materials Characterization*, 62(1), 62–69. <https://doi.org/10.1016/j.matchar.2010.10.012>
- Cho, N. K., Wang, R. Z., Ma, Z., Chen, H., & Xuan, F. Z. (2019). Creep-fatigue endurance of a superheater *tube* plate under non-isothermal loading and multi-dwell condition. *International Journal of Mechanical Sciences*, 161–162(May), 105048. <https://doi.org/10.1016/j.ijmecsci.2019.105048>
- Cicero, S., Lacalle, R., Cicero, R., & García, J. (2010). Failure analysis of a steam generator superheater drain *tube* used in a dump. *Engineering Failure Analysis*, 17(1), 301–312. <https://doi.org/10.1016/j.engfailanal.2009.06.012>
- Dehnavi, F., Eslami, A., & Ashrafizadeh, F. (2017). A case study on failure of superheater *tubes* in an industrial power plant. *Engineering Failure Analysis*, 80, 368–377. <https://doi.org/10.1016/j.engfailanal.2017.07.007>
- Dk, P., & Sh, F. (2014). *Studi Kelayakan Operasi Pipa Furnace A335 P5 Menggunakan Metode Fitness for Services*. *Snttm Xiii*, 15–16.




- Dsilva, P. C., Bhat, S., Banappanavar, J., Kodancha, K. G., & Hegde, S. R. (2021). Premature failure of superheater *tubes* in a fertilizer plant. *Engineering Failure Analysis*, 121(December 2020), 105152. <https://doi.org/10.1016/j.engfailanal.2020.105152>
- Effendi, H. (2008). *Studi Kasus Kegagalan Material ASTM A335 / P12 dalam Aplikasi Boiler Steam Pipe*.
- Evan, B., & Handoyo, E. A. (2013). *Modifikasi Water Tube Boiler Untuk Mengurangi Deposit Pada Pipa Superheater*. 1–8.
- Fahrizal. (2013). *Analisa Penyebab Kegagalan Pipa Superheater PT. Rohul Sawit Indah*. 5, 71–78.
- Firdaus, H., Sudarmawan, R. G., Tarigan, S., Mesin, S. T., Teknik, J., Rekeyasa, M., Jakarta, P. N., & A, J. P. G. (2019). *Studi Kasus Penyebab Kegagalan Pada Pipa Waterwall Untuk Meningkatkan Availability Boiler*. 225–233.
- Firouzeh, A., Ranjbar, K., Lari Baghal, S. M., Heidari Kaidan, A., & Mohemi, E. (2018). Failure assessment of ASTM A213-T12 superheater *Boiler tubes* in a natural gas liquid plant. *Engineering Failure Analysis*, 89, 15–27. <https://doi.org/10.1016/j.engfailanal.2018.03.005>
- Golański, G., & Lachowicz, M. M. (2019). Failure cause analysis for the suspension element of *Boiler superheater*. *Engineering Failure Analysis*, 105(July 2018), 490–495. <https://doi.org/10.1016/j.engfailanal.2019.07.024>
- Gupta, G. K., & Chattopadhyaya, S. (2017). Critical failure analysis of superheater *tubes* of coal-based *Boiler*. *Strojnicki Vestnik/Journal of Mechanical Engineering*, 63(5), 287–299. <https://doi.org/10.5545/sv-jme.2016.4188>
- Haezer, E. (2016). *Analisa Kegagalan Riser Wall Tube Nomor 3 Astm a210 Grade a-1 Pada Boiler Pltu Unit 2 Pt X*.
- Haghighat-Shishavan, B., Firouzi-Nerbin, H., Nazarian-Samani, M., Ashtari, P., & Nasirpouri, F. (2019). Failure analysis of a superheater *tube* ruptured in a power plant *Boiler*: Main causes and preventive strategies. *Engineering Failure Analysis*, 98(December 2018), 131–140. <https://doi.org/10.1016/j.engfailanal.2019.01.016>
- Hosseini, R. K., & Yareiee, S. (2019). Failure analysis of *Boiler tube* at a petrochemical plant. *Engineering Failure Analysis*, 106(February), 104146. <https://doi.org/10.1016/j.engfailanal.2019.104146>
- Husen, A., Setiyadi, A., & Cholis, N. (2018). Analisis Tegangan Pipa 043-Gn-31004 Pada Scrub Coloumn Vessel Menuju Vessel Coloumn Proyek Tangguh Expansion Train 3 Papua. *Bina Teknika*, 14(2), 139. <https://doi.org/10.54378/bt.v14i2.342>
- Jones, D. R. H. (2004). Creep failures of overheated *Boiler*, superheater and reformer *tubes*. *Engineering Failure Analysis*, 11(6), 873–893. <https://doi.org/10.1016/j.engfailanal.2004.03.001>
- Kim, Y. S., Kim, W. C., & Kim, J. G. (2019). Bulging rupture and caustic corrosion


- of a *Boiler tube* in a thermal power plant. *Engineering Failure Analysis*, 104(November 2017), 560–567. <https://doi.org/10.1016/j.engfailanal.2019.06.022>
- Krisdiyanto, K., Fikri, M. N., Adi, R. K., & Nugroho, A. R. A. (2021). Stress Analysis on *Tubesheet* Referring to TEMA Standard. *JMPM (Jurnal Material Dan Proses Manufaktur)*, 5(1), 52–57. <https://doi.org/10.18196/jmpm.v5i1.12340>
- Liu, W. (2021). A superheater creep-fatigue interaction failure and its stress assessment. *Engineering Failure Analysis*, 119(March 2017), 105004. <https://doi.org/10.1016/j.engfailanal.2020.105004>
- Lusiana, L., Citrawati, F., Martides, E., & Gumilar, G. (2019). Analisis Kegagalan Pipa *Boiler Superheater* Pada Pabrik Kelapa Sawit. *DINAMIKA : Jurnal Ilmiah Teknik Mesin*, 11(1), 26. <https://doi.org/10.33772/djitm.v11i1.9357>
- Movahedi-Rad, A., Plasseyed, S. S., & Attarian, M. (2015). Failure analysis of superheater *tube*. *Engineering Failure Analysis*, 48(November), 94–104. <https://doi.org/10.1016/j.engfailanal.2014.11.012>
- Othman, H., Purbolaksono, J., & Ahmad, B. (2009). Failure investigation on deformed superheater *tubes*. *Engineering Failure Analysis*, 16(1), 329–339. <https://doi.org/10.1016/j.engfailanal.2008.05.023>
- Pástor, M., Lengvarský, P., Trebuňa, F., & Čárák, P. (2020). Prediction of failures in steam *Boiler* using quantification of residual stresses. *Engineering Failure Analysis*, 118, 104808. <https://doi.org/10.1016/j.engfailanal.2020.104808>
- Permana, R. H. (2014). Analisa Kerusakan Superheater *Tube* Pada *Boiler* 31F-28 Di Pt Badak. *Jurnal Teknik Pomits*, 1(2). <http://digilib.its.ac.id/public/ITS-paper-31958-2107100074-paper.pdf>
- Purbolaksono, J., Ahmad, J., Beng, L. C., Rashid, A. Z., Khinani, A., & Ali, A. A. (2010). Failure analysis on a primary superheater *tube* of a power plant. *Engineering Failure Analysis*, 17(1), 158–167. <https://doi.org/10.1016/j.engfailanal.2009.04.017>
- Putra, A. A., Prasojo, B., & Sidi, P. (2017). Analisa Kerusakan Water Wall *Tube* Pada Coal *Boiler* (Studi Kasus PT Ecogreen Oleochemicals Batam). *Conference of Piping Engineering and Its Application (CPEAA)*, 1(1), 1–4.
- Rahman, M. M., Purbolaksono, J., & Ahmad, J. (2010). Root cause failure analysis of a division wall superheater *tube* of a coal-fired power station. *Engineering Failure Analysis*, 17(6), 1490–1494. <https://doi.org/10.1016/j.engfailanal.2010.05.005>
- Sari, L. N. (2014). Kerusakan *Tube* Furnace Akibat Deposit Dan Korosi Sulfida Di Industri Migas = the Failure of Furnace *Tube* Caused By Deposit and Sulfide Corrosion in Migas Industry. *Material Komponen Dan Konstruksi*, 14(1), 1. <https://doi.org/10.29122/mkk.v14i1.1649>
- Senthur Prabu, S., Choudhary, A., Mittal, N., Gupta, S., Ramkumar, D., &

- Natarajan, A. (2019). Failure evaluation of SA 210C riffle water wall *tubes* in 70 MW CFBC Boiler. *Engineering Failure Analysis*, 95(June 2017), 239–247. <https://doi.org/10.1016/j.engfailanal.2018.09.028>
- Shokouhmand, H., Ghadimi, B., & Espanani, R. (2015). Failure analysis and retrofitting of superheater *tubes* in utility Boiler. *Engineering Failure Analysis*, 50, 20–28. <https://doi.org/10.1016/j.engfailanal.2015.01.003>
- Vander Voort, G. (2004). Color metallography Vol. 9 ASM handbook. *Metallography and Microstructures*, 9(August), 493–512. <https://doi.org/10.1361/asmhba0003752>
- Wuhan Qingyuan Electric Co. (2012). *Operation Manual Turbine. PLTU Sulawesi Selatan 2×50 MW Coalfired Steam Power Plant.*
- Yue, Z. (2012). Analysis of coated-after superheater pipe bursting accident in utility Boiler. *Procedia Engineering*, 43, 594–599. <https://doi.org/10.1016/j.proeng.2012.08.105>


LAMPIRAN

Lampiran 1. Laporan Kerusakan


			
LAPORAN GANGGUAN / KERUSAKAN PEMBANGKIT UNIT 1 Tanggal 25 November 2021			
Merek	: Nanjing Turbine & Electric Machinery	Daya mampu	: 50 MW
Tipe	: QFW-60-2	JSMO/MI/SE	:
Nomor seri	: 200902004	PLTU	: Barru
Daya Terpasang	: 50 MW	Sektor/Area	: Tello
1. Waktu Kejadian Gangguan	: 25 November 2021 pukul 09:00 WITA		
2. Urutan Kejadian Gangguan	: * 25 November 2021 pukul [08:05] unit 1 beroperasi normal dengan parameter operasi sebagai berikut :		
	Beban Bruto	: 41.9 MW	
	Feed Water Flow	: 217.43 t/h	
	Main Steam Flow	: 182.86 t/h	
	Main Steam Pressure	: 8.76 MPa	
	Main Steam Temperature	: 539.7 °C	
	Upper Pressure Furnace	: -82.93 Pa	
	Temp. Furnace Side A	: 896.9 °C	
	Temp. Furnace Side B	: 916.6 °C	
	Pressure Windbox Furnace	: 13.2 kPa	
	* 25 November 2021 pukul [09:00] upper furnace pressure hunting ke + 700 Pa, disertai terjadi kenaikan pemakaian air, selisih antara feed water flow dengan main steam flow sebanyak 35 t/h dengan parameter operasi sebagai berikut :		
	Beban Bruto	: 41.9 MW	
	Feed Water Flow	: 217.43 t/h	
	Main Steam Flow	: 182.86 t/h	
	Main Steam Pressure	: 8.76 MPa	
	Main Steam Temperature	: 539.7 °C	
	Upper Pressure Furnace	: + 700 Pa	
	Temp. Furnace Side A	: 896.9 °C	
	Temp. Furnace Side B	: 916.6 °C	
	Pressure Windbox Furnace	: 13.2 kPa	
	* 25 November 2021 pukul [22:00] beban diturunkan perlahan guna mengamankan parameter operasi, namun perbandingan feedwater flow dan main steam flow mencapai 33 t/h, dengan parameter operasi sebagai berikut :		
	Beban Bruto	: 23.98 MW	
	Feed Water Flow	: 147.64 t/h	
	Main Steam Flow	: 114.64 t/h	
	Main Steam Pressure	: 7.37 MPa	
	Main Steam Temperature	: 515.9 °C	
	Upper Pressure Furnace	: -80.1 Pa	
	Temp. Furnace Side A	: 846.2 °C	
	Temp. Furnace Side B	: 883.0 °C	
	Pressure Windbox Furnace	: 13.1 kPa	
	* 25 November 2021 pukul [23:22] unit 1 lepas parallel		
3. Indikasi Gangguan	: * Kenaikan pressure upper furnace dari -66.29 Pa ke +2189.91 Pa * Penurunan pressure windbox dari 12.7 kPa ke 13.7 kPa * Selisih flow feedwater dengan flow main steam hingga 42.7 t/h * Level hotweel dan deaerator drop karena pemakaian air tinggi		
4. Penyebab Gangguan	: Kebocoran air di furnace		
5. Peralatan yang terganggu/rusak	: Boiler		
6. Usaha-usaha pemulihan	: Stop unit untuk perbaikan di area boiler		
7. Lama pemulihan	: 12 hari		
8. Akibat gangguan terhadap sistem	: Supply daya ke sistem jaringan terganggu, sehingga sistem kekurangan daya		
9. Kerugian akibat gangguan	: Produksi listrik Unit 1 terhenti (Tidak dapat men-supply daya ke sistem jaringan)		
Supervisor Operasi PLTU Barru OMU		Manager Unit PLTU Barru OMU	
 Ari Adi Sasmita		 Ariy Prabadi	



Lampiran 2. Diagram skema Boiler dan parameter normal operasi di beban Maksimal 50 MW



Lampiran 3. Skema Diagram Main Steam Boiler dan parameter normal operasi di beban Maksimal 50 MW



Lampiran 4. Line Pipa Boiler

