

DAFTAR PUSTAKA

- Ali, Tan. 2013. *Double Bottom*. Diakses pada 03 September 2020.
<http://konstruksikapal.blogspot.com/2013/04/double-bottomsistem-konstruksi-kapal.html>.
- ABS. 2008. *Materials and Welding*. Texas. United States.
- Bai, Y. 2003. *Marine Structural Design*. Elsevier.
- BKI. 2018. *Common Structural Rules for Bulk Carrier and Oil Tanker*.
Jakarta. Indonesia
- BKI. 2019. *Rules for Hull*. Jakarta. Indonesia
- Chakrabarti, S.K. 2005. *Hand Book of Offshore Engineering*. Elsevier. United States.
- Chen, NZ. 2016. *Hull girder reliability assessment for FPSOs*. Elsevier.
- DNV GL. 2017a. *Rules for Classification: Ships, Pt.3 Ch.4. Loads*. Norway.
- DNV GL. 2017b. *Rules for Classification: Ships, Pt.3 Ch.5. Hull Girder Strength*. Norway.
- Hughes, O.F. & Paik, J.K. 2010. *Ship Structural Analysis and Design*. The Society of Naval Architects and Marine Engineers-SNAME, New Jersey.
- IACS. 2014. *Common Structural Rules for Bulk Carriers and Oil Tanker*. London. UK.
- IACS. 2016. *Requirements Concerning of Strength of Ship*. London. UK.
- Kitarović, S. & Andrić, J. 2014. "DATAS D4.0a, b, d State - Of - The - Art I Hull Girder Progressive Collapse Analysis. University of Zagreb", Faculty of Mechanical Engineering and Naval Architecture
- Muis Alie, M.Z. 2018. *The Ultimate Hull Girder Strength Analysis Considering Section Modulus Under Longitudinal Bending. Proceedings of the Twenty-eighth (2018) International Ocean and Polar Engineering Conference*.

- Muis Alie, M.Z. 2018. *Study on ultimate strength of ship's hull considering cross section and beam finite element. ISOCEEN 2018.*
- Muis Alie, M.Z. 2018. *Simplified Approach on the Ultimate Hull Girder Strength of Asymmetrically Damaged Ships. International Journal of Offshore and Polar Engineering (ISSN 1053-5381).*
- Muis Alie, M.Z. 2018. *Investigation of Ship Hull Girder Strength with Grounding Damage. Makara J. Technol. 22/2 (2018), 88-93.*
- Molland, A.F. 2008. *The Maritime Engineering Reference Book.* UK
- Oilgascourse.com. 2012. *FPSO Topside.* Diakses pada 05 Oktober 2020, dari https://oilgascourse.com/ogc/wp-content/uploads/2012/10/oilgascourse_com_FPSO-Topside-Fatigue-Analysis-Training2.html.
- Paik, J.K & Thayambali, A.K. 2007. *Ship Shaped Offshore installation design, building, and operation.* Cambridge Press. America.
- Paik J.K, Kim B.J, Seo J.K. 2008, *Methods for ultimate limit state assessment of ships and ship shaped offshore structures - Part III: Hull girders, Ocean Engineering 35, pp.281-286*
- Piscopo, P. dan Scamardella, A. 2019. "Sensitivity analysis of hull girder reability in intact condition based behavior of whole ship model under extreme waves using idealized structural unit method". *Marine Structures.*
- Shama, M. 2013. *Buckling of Ship Structures.* Springer, Verlag Berlin Heidelberg.
- Tupper, E.C. 2004. *Introduction to Naval Architecture Fourth Edition.* Elsevier.

LAMPIRAN

Lampiran 1. Tabel Hubungan Momen Kelengkungan Kapal FPSO menurut Aturan BKI saat kondisi *sagging* dan *hogging*

CURVATURE	MOMEN
0,370386	1,19949E+12
0,370344	1,19979E+12
0,358352	1,20004E+12
0,336342	1,20019E+12
0,294318	1,20027E+12
0,252282	1,20029E+12
0,21024	1,00027E+12
0,1681924	8,0023E+11
0,126141	6,00162E+11
0,0840704	3,99998E+11
0,0420348	1,99998E+11
0	0
-0,0420348	-2,00002E+11
-0,0840688	-4,00001E+11
-0,1261012	-5,99997E+11
-0,153415	-6,82643E+11
-0,1669352	-6,42643E+11
-0,1929352	-6,42643E+11
-0,2029352	-6,42643E+11
-0,2230352	-6,42643E+11

Lampiran 2. Tabel Hubungan Momen Kelengkungan Kapal FPSO menurut Aturan IACS saat kondisi *sagging* dan *hogging*

CURVATURE	MOMEN
1,873E-01	5,5303E+11
1,863E-01	5,52032E+11
1,643E-01	5,51991E+11
1,456E-01	5,48361E+11
1,275E-01	6,00639E+11
1,061E-01	5E+11
7,076E-02	3,33334E+11
3,538E-02	1,66668E+11
0	0
-4,246E-02	-1,99998E+11
-8,492E-02	-3,99998E+11
-1,274E-01	-6,00049E+11
-1,698E-01	-7,99932E+11
-2,122E-01	-9,99705E+11
-2,425E-01	-1,1421E+12
-2,731E-01	-1,1331E+12
-2,931E-01	-1,1321E+12
-3,131E-01	-1,1331E+12
-3,331E-01	-1,1331E+12