



DAFTAR PUSTAKA



- Baskari,T.L. 2008. *Kajian Klasifikasi Massa Batuan Terhadap Stabilitas Lereng dan Penentuan Kekuatan Jangka Panjangnya pada Operasi Penambangan Binungan PT. Berau Coal Kalimantan Timur.* Bandung: Fakultas Teknik Pertambangan dan Perminyakan ITB.
- Bieniawski, Z.T., 1976. *Rock Mass Classification in Rock Engineering. In Exploration for rock engineering, proc. of the symp.*, (ed. Z.T. Bieniawski) 1, 97-106. Cape Town: Balkema.
- Bieniawski, Z.T., 1989, *Engineering Rock Mass Classifications*, Wiley, New York, pp.251.
- Das, B.M. 2010. *Principles of Geotechnical Engineering, 7th Edition.* Stamfprd: Cengage Learning.
- Deere, D.U., Hendron, A.J., Patton, F.D. and Cording, E.J. 1989. *Design of surface and near surface construction rock. In Failure and breakage of rock*, proc. 8th U.S. symp. Rock mech., (ed. C. Fairhurst), 237-302. New York: Soc. Min. Engrs, Am. Inst. Min. Metall. Petrolm Engrs.
- Franklin, J. A., and Maerz, N. H., 1996. t. Proceedings of the FRAGBLAST 5 Workshop on Measurement of Blast Fragmentation, Montreal, Quebec, Canada, 23-24 Aug., 1996, pp. 193-201.
- Gautama, R.S. Pramono, Y.B. 1991. *Kemantapan Lereng di Pertambangan Indonesia.* Bandung:ITB.
- Giani, G.P. 1992. *Rock Slope Stability Analysis.* Rotterdam: A.A. Balkema Publishers.
- Hoek, E., 1990, *Estimating Mohr-Coulomb Friction and Cohesion Values from the Hoek- Brown Failure Criterion*, International Journal Rock Mechanic and Mining Science, Vol.27, pp. 227-229.
- Hoek, E., and Bray.J.W., 1981, *Rock Slope Engineering 3rd edition*, London: Institution of Mining and Metallurgy.
- Hoek, E. and Brown, E.T., 1980, *Empirical Strength Criterion for Rock Masses*, Journal of the Geotechnical Engineering, pp. 1013-1035.
- Hoek, E. and Brown, E.T., 1998a, *Practical Estimates of Rock Mass Strength*, International Journal of Rock Mechanic and Mining Science, Vol.34, pp. 1165-1186.
- Hoek, E., Kaiser, P.K., and Bawde, W.F. 1998b. *Support of Underground Excavations In Hard Rock.* Balkema: New York.


- Hoek, E., Torres C.C., and Corkum, B., 2002, *Hoek-Brown Failure Criterion*, Mining Innovation and Technology, University of Toronto, pp. 267-273.
- Hudson, J., 1997. *Comprehensive Rock Engineering Principles, Practice, and Projects*, vol 3. Pergamon Press: New York.
- Krahn, J., 2004, *Stability Modeling with SLOPE/W: An Engineering Methodology*, GEO SLOPE Internatonal Ltd: Canada.
- Liong, G.T. and Herman, D.J.G. 2012. *Analisa Stabilitas Lereng Limit Equilibrium vs Finite Element Method*. Prosiding HATTI-PTI-XVI 2012. Jakarta.
- Maerz, N.H., 2000. *Highway Rock Cut Stability Assesment in Rock Masses Not Conducive to Stability Calculations*, Proceedings of the 51st Annual Highway Geology Symposium, Seattle, Washington, Augustus 29 - September 1, 2000. pp. 249-259.
- Morgenstern, N.R., and Price, V.E., 1965, *The Analysis of The Stability of General Slip Surfaces*, International Journal of the Geotechnical Engineering, Vol. 15, pp. 79- 93.
- Pagemanan, V.G.M. Turangan, A.E. Sompie, O.B.A. 1991. *Analisis Kestabilan Lereng dengan Metode Fellenius*. Jurnal Sipil Statik 2(1):37-46.
- Read, J. Peter, S. 2010. *Open Pit Slope Design*. Canberra: CSIRO.
- Romana, M. R. 1993. *A Geomechanical Classification for Slopes: Slope Mass Rating*, Comprehensive Rock Engineering. Pergamon Press, New York, Vol 3, pp; 575 -600.
- Syaeful, H.. 2012. *Potensi dan Bentuk Bidang Runtuhan pada Lereng Tambang Terbuka*, Pusat Pengembangan Geologi Nuklir, Prosiding Jakarta, Hal. 99-120.
- Terzaghi, K. and Peck, R.B. 1987. *Soil Mechanics in Engineering Practice, Second Edition*. John Wiley and Sons, Inc
- Umrao, R.K., Singh, R., Ahmad, M., and Singh, T.N., 2011, *Stability Analysis of Cut Slope Using Continuous Slope Mass Rating and Kinematic Analysis*, Indian Geomaterials Journal, Vol. 1, No. 3.
- Varnes, D. J. 1978. *Slope Movement Types and Process, Eckel EB (ed) Landslides and Engineering Practice*, Special Report 28:, Highway Research Board. National Academy of Science, Washington D.C. pp; 20-47.


LAMPIRAN

**Lampiran 1 (Material Properties Waste & Buttress In-Pit Dump
Seam 28-29)**

|  ZEKON INDONESIA <small>INTEGRATED ENGINEERING AND CONSTRUCTION</small> Website : www.zekon.co.id Email : info@zelon.co.id | TECHNICAL NOTE |  <small>PT JEMBAYAN MUARABARA</small> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|--|---|---------------------------------------|---------------------------------------|-------------------------------|-------------------------------|---------------|---------------|--------------------------|---------|----|----|-----------|---|------|----|--------------|----|----|--|---------------|--------------------------|---|--|----------|---|----|------|-----------|----|--|----------|------|--|--|---|-----------|---|----|----|-----------|-----|--|----------|------|--|--|---|---------------|---|------|----|--------------|-----|----|--|---------------|--------------------------|---|--|----------|---|----|----|--------------|-----|----|--|---------------|--------------------------|---|--|------|---|----|------|-----------|----|--|----------|------|--|--|---|------|---|----|------|-----------|----|--|--------|------|--|--|---|---------|---|----|------|-----------|----|--|----------|------|--|--|---|
| Client : PT. JEMBAYAN MUARABARA (JMB) | Date : September 26 th , 2019 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Project : Slope Stability Analysis of IPD 303 JMB | Attention : Komang Suandra | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Location : District of Separi - East Kalimantan | : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Subject : Slope Stability Analysis | : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 6. SUMMARY OF MATERIAL PROPERTIES | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Summary of material properties that is used in slope stability analysis is presented as follow: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <table border="1"> <thead> <tr> <th>Material Name</th> <th>Color</th> <th>Unit Weight (kN/m³)</th> <th>Sat. Unit Weight (kN/m³)</th> <th>Strength Type</th> <th>Cohesion (kN/m²)</th> <th>Phi</th> <th>Cohesion Type</th> <th>Water Surface</th> <th>Hu Type</th> <th>Hu</th> <th>Ru</th> </tr> </thead> <tbody> <tr> <td>COAL Seam</td> <td>■</td> <td>12.5</td> <td>13</td> <td>Mohr-Coulomb</td> <td>10</td> <td>15</td> <td></td> <td>Water Surface</td> <td>Automatically Calculated</td> <td>1</td> <td></td> </tr> <tr> <td>Buttress</td> <td>■</td> <td>17</td> <td>17.5</td> <td>Undrained</td> <td>70</td> <td></td> <td>Constant</td> <td>None</td> <td></td> <td></td> <td>0</td> </tr> <tr> <td>CLAYSTONE</td> <td>■</td> <td>19</td> <td>20</td> <td>Undrained</td> <td>300</td> <td></td> <td>Constant</td> <td>None</td> <td></td> <td></td> <td>0</td> </tr> <tr> <td>Bedding Shear</td> <td>■</td> <td>12.5</td> <td>13</td> <td>Mohr-Coulomb</td> <td>223</td> <td>55</td> <td></td> <td>Water Surface</td> <td>Automatically Calculated</td> <td>1</td> <td></td> </tr> <tr> <td>Interbed</td> <td>■</td> <td>19</td> <td>20</td> <td>Mohr-Coulomb</td> <td>157</td> <td>59</td> <td></td> <td>Water Surface</td> <td>Automatically Calculated</td> <td>0</td> <td></td> </tr> <tr> <td>WD-1</td> <td>■</td> <td>16</td> <td>16.5</td> <td>Undrained</td> <td>50</td> <td></td> <td>Constant</td> <td>None</td> <td></td> <td></td> <td>0</td> </tr> <tr> <td>WD-2</td> <td>■</td> <td>16</td> <td>16.5</td> <td>Undrained</td> <td>50</td> <td></td> <td>FDepth</td> <td>None</td> <td></td> <td></td> <td>0</td> </tr> <tr> <td>Stage 6</td> <td>■</td> <td>16</td> <td>16.5</td> <td>Undrained</td> <td>50</td> <td></td> <td>Constant</td> <td>None</td> <td></td> <td></td> <td>0</td> </tr> </tbody> </table> | Material Name | Color | Unit Weight (kN/m ³) | Sat. Unit Weight (kN/m ³) | Strength Type | Cohesion (kN/m ²) | Phi | Cohesion Type | Water Surface | Hu Type | Hu | Ru | COAL Seam | ■ | 12.5 | 13 | Mohr-Coulomb | 10 | 15 | | Water Surface | Automatically Calculated | 1 | | Buttress | ■ | 17 | 17.5 | Undrained | 70 | | Constant | None | | | 0 | CLAYSTONE | ■ | 19 | 20 | Undrained | 300 | | Constant | None | | | 0 | Bedding Shear | ■ | 12.5 | 13 | Mohr-Coulomb | 223 | 55 | | Water Surface | Automatically Calculated | 1 | | Interbed | ■ | 19 | 20 | Mohr-Coulomb | 157 | 59 | | Water Surface | Automatically Calculated | 0 | | WD-1 | ■ | 16 | 16.5 | Undrained | 50 | | Constant | None | | | 0 | WD-2 | ■ | 16 | 16.5 | Undrained | 50 | | FDepth | None | | | 0 | Stage 6 | ■ | 16 | 16.5 | Undrained | 50 | | Constant | None | | | 0 |
| Material Name | Color | Unit Weight (kN/m ³) | Sat. Unit Weight (kN/m ³) | Strength Type | Cohesion (kN/m ²) | Phi | Cohesion Type | Water Surface | Hu Type | Hu | Ru | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| COAL Seam | ■ | 12.5 | 13 | Mohr-Coulomb | 10 | 15 | | Water Surface | Automatically Calculated | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Buttress | ■ | 17 | 17.5 | Undrained | 70 | | Constant | None | | | 0 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CLAYSTONE | ■ | 19 | 20 | Undrained | 300 | | Constant | None | | | 0 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Bedding Shear | ■ | 12.5 | 13 | Mohr-Coulomb | 223 | 55 | | Water Surface | Automatically Calculated | 1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Interbed | ■ | 19 | 20 | Mohr-Coulomb | 157 | 59 | | Water Surface | Automatically Calculated | 0 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| WD-1 | ■ | 16 | 16.5 | Undrained | 50 | | Constant | None | | | 0 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| WD-2 | ■ | 16 | 16.5 | Undrained | 50 | | FDepth | None | | | 0 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Stage 6 | ■ | 16 | 16.5 | Undrained | 50 | | Constant | None | | | 0 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7. SURCHARGE LOAD | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| The using of HD 785-7 Komatsu will be generating great surcharge load over disposal area. Technical specification of HD 785-7 can be seen below: | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|  | WEIGHT (APPROX.)  Empty weight 72.600 kg Gross vehicle weight 166.000 kg Not to exceed max. gross vehicle weight, including options, fuel and payload. Weight distribution Empty: Front axle 47% Rear axle 53% Loaded: Front axle 31,5% Rear axle 68,5% | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|  | TYRES  Standard tyres 27.00 R49 Overall width = 758 mm Overall diameter = 2697 mm Estimated contact area = 0.575 m ² | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Design surcharge load shall be empty weight plus permissible payload divided by estimated contact area that has considered the weight distribution. For 80% of max. payload, the design surcharge load is 433 kPa. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

|  ZEKON INDONESIA <small>INTEGRATED ENGINEERING AND CONSTRUCTION</small> Website : www.zekon.co.id Email : info@zekon.co.id | TECHNICAL NOTE |  <small>PT JEMBAYAN MUARABARA</small> | | | | | | | |
|--|--|---|------------|---------------|-----|----|-------------------|-----|----|
| Client : PT. JEMBAYAN MUARABARA (JMB) | Date : September 26 th , 2019 | | | | | | | | |
| Project : Slope Stability Analysis of IPD 303 JMB | Attention : Komang Suandra | | | | | | | | |
| Location : District of Separi - East Kalimantan | : | | | | | | | | |
| Subject : Slope Stability Analysis | : | | | | | | | | |
| 3. PARAMETER SELECTION OF COAL SEAM 28L & INTERBED MATERIAL | | | | | | | | | |
| Laboratory testing results for coal seam 28L and interbed material is presented as follow: | | | | | | | | | |
|  <p>Horizontal Stress (kg/cm^2)</p> <p>Normal Stress (kg/cm^2)</p> <p>$y = 1.4321x + 2.2781$</p> <p>BR 01-01 (Peak) (Red Diamond) BR 02-01 (Peak) (Blue Square) BR 03-01 (Peak) (Green Triangle) Linear (Avg Peak) (Black Dashed Line)</p> <p>Coal Seam 28L</p> |  <p>Horizontal Stress (kg/cm^2)</p> <p>Normal Stress (kg/cm^2)</p> <p>BR 01-01 (Peak) (Red Diamond) BR 02-01 (Peak) (Blue Square) BR 03-01 (Peak) (Green Triangle) BR 01-01(2) (Peak) (Yellow Circle) BR 02-01(2) (Peak) (Purple Plus) Linear (Avg Peak) (Black Dashed Line) Linear (Avg Peak) (Blue Dashed Line)</p> <p>$y = 1.7156x + 1.6012$</p> <p>Interbed Material</p> | | | | | | | | |
| Summary strength properties of coal seam 28L and interbed material is presented as follow: | | | | | | | | | |
| <table border="1"> <thead> <tr> <th>Soil Type</th> <th>c (kPa)</th> <th>ϕ (°)</th> </tr> </thead> <tbody> <tr> <td>Coal Seam 28L</td> <td>223</td> <td>55</td> </tr> <tr> <td>Interbed Material</td> <td>157</td> <td>59</td> </tr> </tbody> </table> | Soil Type | c (kPa) | ϕ (°) | Coal Seam 28L | 223 | 55 | Interbed Material | 157 | 59 |
| Soil Type | c (kPa) | ϕ (°) | | | | | | | |
| Coal Seam 28L | 223 | 55 | | | | | | | |
| Interbed Material | 157 | 59 | | | | | | | |
| <p>Comment: Both coal seam 28L and interbed material should not be the trigger of encountered problem as predicted earlier. The laboratory results above showed good condition of coal seam 28L & interbed material as well as the existing condition as depicted below:</p> | | | | | | | | | |
|  <p>Excavated Coal Seam 28L & Interbed Material</p> |  <p>Condition of Coal Seam 28L & Interbed Material</p> | | | | | | | | |





| | | |
|---|--|---|
|  ZEKON INDONESIA <small>INTEGRATED ENGINEERING AND CONSTRUCTION</small> Website : www.zekon.co.id Email : info@zekon.co.id | <u>TECHNICAL NOTE</u> |  <small>PT JEMBAYAN MUARABARA</small> |
| Client : PT. JEMBAYAN MUARABARA (JMB) Project : Slope Stability Analysis of IPD 303 JMB Location : District of Separi - East Kalimantan Subject : Slope Stability Analysis | Date : September 26 th , 2019 Attention : Komang Suandra : : | |

1. PROBLEM

ZEKON has been invited by JMB to provide technical analysis to solve problem encountered at Input Dump 303 JMB. Our team visited the site on July 2019 to collect important information such as field documentations and other required data. General findings that encountered at IPD 303 JMB mentioned as follow:

- Crack line on RL +40 m
- Crack line on RL +0 m
- Crack line at toe of buttress
- Ground subsidence along the crack line on RL +40 m



North

30 m

+40 m

+30 m

+20 m

+10 m

Juli 2019




CRACKS

CRACKS

CRACKS

BUTTRESS TOE




CRACKS

CRACKS

CRACKS

RL. +40 m



CRACKS


CRACKS

RL. +0 m

Preliminary suspect that generate problem on IPD 303 JMB is the bedding shear of coal seam 28L. Further action to prove this problem is by collecting core samples from 3 (three) boreholes (BR-01, BR-02 and BR-03) along the toe of buttress.

Collected data that collected during site visit is listed as follow:



- Topographic maps (July 1st and 19th, 2019)
- Design stage of IPD 303 JMB (Stage 1 through 7)
- Design report (Golder, 2018)
- Monitoring data in period of July 18th through 20th (PAMA, 2019)
- Material specification of buttress (Requirement : DCP < 10 blows/100 mm)



|  ZEKON INDONESIA <small>INTEGRATED ENGINEERING AND CONSTRUCTION</small> Website : www.zekon.co.id Email : info@zekon.co.id | <u>TECHNICAL NOTE</u> |  <small>PT JEMBAYAN MUARABARA</small> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|--|---|----|---|-------------|-----------|-------------|-------|-------|-------|-------------|--------------|----|---|-------|-------------|--------------|----|---|-------|-------------|--------------|----|---|-------|-------------|--------------|----|----------------------------------|-------|-------------|--------------|----|------------------------------------|-------|-------------|--------------|----|------------------------------------|-------|-------------|--------------|----|------------------------------------|-------|-------------|--------------|----|------------------------------------|
| Client : PT. JEMBAYAN MUARABARA (JMB) | Date : September 26 th , 2019 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Project : Slope Stability Analysis of IPD 303 JMB | Attention : Komang Suandra | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Location : District of Separi - East Kalimantan | : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Subject : Slope Stability Analysis | : | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p>2. REQUEST OF GEOTECHNICAL DRILLING</p> <p>ZEKON has requested JMB to provide geotechnical drilling at IPD 303 JMB in order to assess soil properties required for performing slope stability analysis. General layout of geotechnical drilling is depicted as follow:</p>  <p style="text-align: center;">Layout of Geotechnical Drilling</p> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th rowspan="2">ID</th> <th colspan="2">Coordinates</th> <th rowspan="2">Depth (m)</th> <th rowspan="2">Requirement</th> </tr> <tr> <th>x (m)</th> <th>y (m)</th> </tr> </thead> <tbody> <tr> <td>BR-01</td> <td>516378.6411</td> <td>9982739.5090</td> <td>15</td> <td>Collect core sample of seam 28L & interbed material</td> </tr> <tr> <td>BR-02</td> <td>516674.7676</td> <td>9982547.9042</td> <td>15</td> <td>Collect core sample of seam 28L & interbed material</td> </tr> <tr> <td>BR-03</td> <td>516979.2156</td> <td>9982471.3585</td> <td>15</td> <td>Collect core sample of seam 28L & interbed material</td> </tr> <tr> <td>BR-04</td> <td>516680.2993</td> <td>9982702.6240</td> <td>40</td> <td>SPT and UDS on buttress material</td> </tr> <tr> <td>BR-05</td> <td>516899.8928</td> <td>9982827.3502</td> <td>45</td> <td>SPT and UDS on waste dump material</td> </tr> <tr> <td>BR-06</td> <td>517060.4628</td> <td>9982995.2876</td> <td>50</td> <td>SPT and UDS on waste dump material</td> </tr> <tr> <td>BR-07</td> <td>516778.6537</td> <td>9982769.9406</td> <td>25</td> <td>SPT and UDS on waste dump material</td> </tr> <tr> <td>BR-08</td> <td>516985.6493</td> <td>9982900.2165</td> <td>25</td> <td>SPT and UDS on waste dump material</td> </tr> </tbody> </table> <p>Samples collected from field have been delivered and tested in laboratory to assess the following properties:</p> <ul style="list-style-type: none"> Index properties (particle size distribution, natural water content, bulk density, specific gravity, atterberg limit) Strength properties (direct shear test, unconfined compression test, Triaxial UU) | | | ID | Coordinates | | Depth (m) | Requirement | x (m) | y (m) | BR-01 | 516378.6411 | 9982739.5090 | 15 | Collect core sample of seam 28L & interbed material | BR-02 | 516674.7676 | 9982547.9042 | 15 | Collect core sample of seam 28L & interbed material | BR-03 | 516979.2156 | 9982471.3585 | 15 | Collect core sample of seam 28L & interbed material | BR-04 | 516680.2993 | 9982702.6240 | 40 | SPT and UDS on buttress material | BR-05 | 516899.8928 | 9982827.3502 | 45 | SPT and UDS on waste dump material | BR-06 | 517060.4628 | 9982995.2876 | 50 | SPT and UDS on waste dump material | BR-07 | 516778.6537 | 9982769.9406 | 25 | SPT and UDS on waste dump material | BR-08 | 516985.6493 | 9982900.2165 | 25 | SPT and UDS on waste dump material |
| ID | Coordinates | | | Depth (m) | Requirement | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | x (m) | y (m) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-01 | 516378.6411 | 9982739.5090 | 15 | Collect core sample of seam 28L & interbed material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-02 | 516674.7676 | 9982547.9042 | 15 | Collect core sample of seam 28L & interbed material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-03 | 516979.2156 | 9982471.3585 | 15 | Collect core sample of seam 28L & interbed material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-04 | 516680.2993 | 9982702.6240 | 40 | SPT and UDS on buttress material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-05 | 516899.8928 | 9982827.3502 | 45 | SPT and UDS on waste dump material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-06 | 517060.4628 | 9982995.2876 | 50 | SPT and UDS on waste dump material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-07 | 516778.6537 | 9982769.9406 | 25 | SPT and UDS on waste dump material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BR-08 | 516985.6493 | 9982900.2165 | 25 | SPT and UDS on waste dump material | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Lampiran 2 (Material Properties Batuan In-Pit Dump Seam 28-29)

| JEMBAYAN MUARA BARA - PIT 303 GEOTECHNICAL DATA FOR EACH MATERIAL (LAYER) | | | | | | | | | | | |
|--|--|------------------|----------------------------|------------------------|--------------|----------|----------------|----------|-----------------------------------|----------|-------------------|
| Name Of Litology | σ_c (Mpa) Compressive Strength | σ_n (Mpa) | E (Mpa) Young's Modulus | ν Poisson Ratio | τ (Mpa) | | Cohesion (Mpa) | | Phi ($^{\circ}$) Friction Angle | | Remarks |
| | | | | | Peak | Residual | Peak | Residual | Peak | Residual | |
| Overburden | 0.70 | | 82.25 | 0.32 | | | | | | | UCS (BH02) |
| | | 0.064 | | | 0.159 | 0.129 | | | | | |
| | | 0.185 | | | 0.253 | 0.193 | | | | | DS (BH02) |
| | | 0.190 | | | 0.257 | 0.196 | | | | | |
| Interburden 1 (Seam 20-22) | 0.70 | | 82.25 | 0.32 | | | | | | | |
| | 9.31 | | 1504.78 | 24.00 | | | | | | | Coal Layer (BH02) |
| | 2.44 | | 183.69 | 0.29 | | | | | | | UCS (BH02) |
| Interburden 2 (seam 22-24) | 3.93 | | 184.27 | 0.26 | | | | | | | UCS (BH02) |
| | 1.44 | | 94.20 | 0.31 | | | | | | | UCS (BH04) |
| | 1.19 | | 119.67 | 0.25 | | | | | | | UCS (BH04) |
| | 2.14 | | 110.20 | 0.31 | | | | | | | UCS (BH05) |
| | 2.18 | | 127.09 | 0.28 | | | | | | | |
| Interburden 3 (seam 24-25) | 0.069 | | | | 0.101 | 0.075 | | | | | |
| | 0.138 | | | | 0.134 | 0.098 | | | | | |
| | 0.206 | | | | 0.166 | 0.12 | | | | | |
| | 0.069 | | | | 0.201 | 0.111 | | | | | |
| | 0.139 | | | | 0.249 | 0.136 | | | | | |
| | 0.201 | | | | 0.291 | 0.159 | | | | | |
| | 0.063 | | | | 0.179 | 0.125 | | | | | |
| | 0.135 | | | | 0.233 | 0.155 | | | | | |
| | 0.184 | | | | 0.269 | 0.175 | | | | | |
| | 0.068 | | | | 0.167 | 0.108 | | | | | |
| | 0.18 | | | | 0.215 | 0.13 | | | | | |
| | 0.208 | | | | 0.262 | 0.153 | | | | | |
| | 1.85 | | 106.33 | 0.31 | | | | | | | UCS (BH04) |
| | 0.25 | | 27.97 | 0.25 | | | | | | | UCS (BH04) |
| Interburden 4 (seam 25-26) | 1.72 | | 95.64 | 0.31 | | | | | | | UCS (BH05) |
| | 0.69 | | 90.17 | 0.31 | | | | | | | UCS (BH05) |
| | 5.99 | | 328.8 | 0.31 | | | | | | | UCS (BH05) |
| | 10.56 | | 442.91 | 0.23 | | | | | | | UCS (BH02) |
| | 2.48 | | 205.06 | 0.3 | | | | | | | UCS (BH01) |
| | 3.36285714 | | 185.2686 | 0.288571 | | | | | | | |
| | 4.95 | | 457.26 | 0.30 | | | | | | | UCS (BH01) |
| Interburden 5 (seam26-28) | 0.25 | | 10.56 | 0.29 | | | | | | | UCS (BH03) |
| | 6.56 | | 428.14 | 0.31 | | | | | | | Coal Layer (BH04) |
| | 0.06 | | | | 0.21 | 1.51 | | | | | |
| | 0.13 | | | | 0.25 | 0.18 | | | | | |
| | 0.20 | | | | 0.30 | 0.21 | | | | | DS (BH05) |
| Interburden 6 (Seam 28-29) | 3.92 | | 298.65 | 0.30 | | | | | | | |
| | 4.92 | | 269.74 | 0.31 | | | | | | | UCS (BH05) |
| | 10.63 | | 1127.86 | 0.25 | | | | | | | UCS (BH04) |
| | 2.94 | | 164.45 | 0.23 | | | | | | | UCS (BH03) |
| | 9.11 | | 909.55 | 0.29 | | | | | | | UCS (BH01) |
| | 0.074 | | | | 0.272 | 0.158 | | | | | |
| | 0.144 | | | | 0.323 | 0.190 | | | | | DS (BH-03) |
| Interburden 7 (seam 29-31) | 0.231 | | | | 0.387 | 0.230 | | | | | |
| | 6.90 | | 617.90 | 0.27 | | | | | | | |
| | 0.52 | | 63.71 | 0.30 | | | | | | | UCS (BH03) |
| | 1.60 | | 110.56 | 0.31 | | | | | | | UCS (BH04) |
| | 4.13 | | 536.85 | 0.25 | | | | | | | UCS (BH05) |
| | 0.068 | | | | 0.120 | 0.075 | | | | | |
| | 0.147 | | | | 0.164 | 0.106 | | | | | |
| | 0.223 | | | | 0.206 | 0.134 | | | | | |
| | 0.067 | | | | 0.106 | 0.069 | | | | | |
| | 0.138 | | | | 0.132 | 0.091 | | | | | |
| Interburden 8 (seam 31-below) | 0.207 | | | | 0.158 | 0.112 | | | | | |
| | 0.055 | | | | 0.134 | 0.104 | | | | | |
| | 0.13 | | | | 0.191 | 0.144 | | | | | |
| | 0.188 | | | | 0.235 | 0.175 | | | | | |
| | 2.08333333 | | 237.04 | 0.286667 | | | | | | | |
| Interburden 7 (seam 29-31) | 0.98 | | 185.46 | 0.24 | | | | | | | UCS (BH01) |
| | 2.16 | | 203.67 | 0.23 | | | | | | | UCS (BH03) |
| Interburden 8 (seam 31-below) | 1.57 | | 194.565 | 0.235 | | | | | | | |
| | 2.02 | | 140.76 | 0.29 | | | | | | | UCS (BH03) |
| | 2.02 | | 140.76 | 0.29 | | | | | | | |


| JEMBAYAN MUARA BARA-PIT 303 SUMMARY OF GEOTECHNICAL DATA | | | | | | | | | | | | |
|---|----------------------------------|------------------------|---------|-----------------|-------|-----|-------|--------|-------|--------------|------------|--------------|
| Name Of Litology | γ (KN/m ³) | Generalised Hoek-Brown | | | | | | | | Mohr-Coulomb | | Remarks |
| | | σ_c (Mpa) | E (Mpa) | Young's Modulus | ν | GSI | mi | mb | s | a | c' (Mpa) | ϕ (deg) |
| Overburden | 22 | 0.70 | 82.25 | 0.32 | 60 | 7 | 1.678 | 0.0117 | 0.503 | 0.038 | 30.36 | |
| Interburden 1 (Seam 20-22) | 22 | 2.44 | 183.69 | 0.29 | 65 | 7 | 2.006 | 0.0205 | 0.502 | 0.145 | 31.76 | |
| Interburden 2 (Seam 22-24) | 22 | 2.18 | 127.09 | 0.28 | 70 | 7 | 2.398 | 0.0357 | 0.501 | 0.146 | 33.12 | |
| Interburden 3 (Seam 24-25) | 22 | 3.36 | 185.27 | 0.29 | 70 | 7 | 2.398 | 0.0357 | 0.501 | 0.225 | 33.12 | |
| Interburden 4 (Seam 25-26) | 22 | 3.92 | 298.65 | 0.30 | 70 | 7 | 2.398 | 0.0357 | 0.501 | 0.263 | 33.12 | |
| Interburden 5 (Seam 26-28) | 22 | 6.90 | 617.90 | 0.27 | 70 | 7 | 2.398 | 0.0357 | 0.501 | 0.462 | 33.12 | |
| Interburden 6 (Seam 28-29) | 22 | 2.08 | 237.04 | 0.29 | 70 | 7 | 2.398 | 0.0357 | 0.501 | 0.139 | 33.12 | |
| Interburden 7 (Seam 29-31) | 22 | 1.57 | 194.57 | 0.24 | 70 | 7 | 2.398 | 0.0357 | 0.501 | 0.105 | 33.12 | |
| Interburden 8 (Seam 31-below) | 22 | 2.02 | 140.76 | 0.29 | 70 | 7 | 2.398 | 0.0357 | 0.501 | 0.135 | 33.12 | |
| Coal (Seam 20-25) | 14 | 9.31 | 1504.78 | 24.00 | 45 | 15 | 2.104 | 0.0022 | 0.508 | 0.487 | 32.49 | |
| Coal (Seam 26-31) | 14 | 6.56 | 428.14 | 0.31 | 45 | 15 | 2.104 | 0.0022 | 0.508 | 0.343 | 32.49 | |






Lampiran 3 (Hasil Analisis Kestabilan Desain Lereng In-Pit Dump Pit 303)


Crossection A




Crosssection B



Crossection C




Crossection D



Lampiran 4 (Hasil Analisis Kestabilan Desain Lereng Rekomendasi *In-Pit Dump* Crossection B & C)

Crossection B



Crossection C

